



Notification of a Proposal to issue an Airworthiness Directive

PAD No.: 22-040

Issued: 04 April 2022

Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EU) 2018/1139 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 129 of that Regulation.

In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below.

All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation date indicated.

Design Approval Holder's Name:

AIRBUS HELICOPTERS

Type/Model designation(s):

AS 355 helicopters

Effective Date: [TBD - standard: 14 days after AD issue date]

TCDS Number(s): EASA.R.146

Foreign AD: Not applicable

Supersedure: None

ATA 65 – Tail Rotor Drive – Fan Assembly – Inspection

Manufacturer(s):

Airbus Helicopters (AH), formerly Eurocopter, Eurocopter France, Aerospatiale

Applicability:

AS 355 E, AS 355 F, AS 355 F1, AS 355 F2 and AS 355 N helicopters, all serial numbers.

Definitions:

For the purpose of this AD, the following definitions apply:

Affected part: Right-hand (RH) side fan supports, having part number (P/N) 355A34-1041-05 or P/N 355A34-1041-03; and left-hand (LH) side fan supports, having P/N 355A34-1040-05 or P/N 355A34-1040-03.

Serviceable part: A fan support, eligible for installation, which is not an affected part. This includes fan supports, having P/N 355A34-1041-06 (RH) or P/N 355A34-1040-06 (LH).

The ASB: AH Alert Service Bulletin (ASB) AS355-05.00.88.

Groups: Group 1 helicopters are those that have an affected part installed. Group 2 helicopters are those that do not have an affected part installed. A helicopter on which Airbus modification (mod)



07-9062 has been embodied in production is a Group 2 helicopter, provided no affected part is installed on that helicopter.

Reason:

An occurrence was reported of RH fan support found partly broken (1 leg among 2) and LH fan support found completely broken (2 legs among 2) during a scheduled maintenance on an AS 355 helicopter. The helicopter was in pre-mod 07-9062 configuration. AH mod 07-9062 consists in modifying the fan support by making the holes from a round to an oblong shape, allowing adjustment of the assembly and removing the stress during assembly. In the past, additional cases were reported of finding ruptured fan support legs on pre-mod 07-9062 helicopters, affecting legs on both RH and LH supports.

This condition, if not detected and corrected, could lead to loss of main gearbox and engine oil cooling function and loss of tail rotor drive, possibly resulting in loss of control of the helicopter.

To address this unsafe condition, AH issued the ASB, providing inspection instructions.

For the reason described above, this AD requires repetitive inspections of the legs of each affected part and, depending on findings, accomplishment of applicable corrective action(s). This AD also prohibits (re)installation of an affected part on a helicopter.

This AD is considered an interim action and further AD action may follow.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspections:

- (1) For Group 1 helicopters: Within 50 flight hours (FH) or 6 months, whichever occurs first after the effective date of this AD, and, thereafter, at intervals not to exceed 50 FH or 6 months, whichever occurs first, inspect the legs of each affected part in accordance with the instructions of the ASB.

Corrective Action(s):

- (2) If, during any inspection as required by paragraph (1) of this AD, any cracked or broken leg is found, before next flight, modify the helicopter by replacing each affected part with a serviceable part in accordance with the instructions of the ASB.

Terminating Action:

- (3) Modification of a helicopter as required by paragraph (2) of this AD constitutes terminating action for the repetitive inspections as required by paragraph (1) of this AD for that helicopter.

Part(s) Installation:

- (4) Do not install an affected part on any helicopter, as required by paragraph (2.1) or (2.2) of this AD, as applicable.
 - (4.1) For Group 1 helicopters: After modification of the helicopter as required by paragraph (2) of this AD.



(4.2) For Group 2 helicopters: From the effective date of this AD.

Ref. Publications:

AH ASB AS355-05.00.88 original issue dated 03 April 2022.

The use of later approved revisions of the above-mentioned document is acceptable for compliance with the requirements of this AD.

Remarks:

1. This Proposed AD will be closed for consultation on 18 April 2022.
2. Enquiries regarding this PAD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
3. Information about any failures, malfunctions, defects or other occurrences, which may be similar to the unsafe condition addressed by this PAD, and which may occur, or have occurred on a product, part or appliance not affected by this PAD, can be reported to the [EU aviation safety reporting system](#). This may include reporting on the same or similar components, other than those covered by the design to which this PAD applies, if the same unsafe condition can exist or may develop on an aircraft with those components installed. Such components may be installed under an FAA Parts Manufacturer Approval (PMA), Supplemental Type Certificate (STC) or other modification.
4. For any question concerning the technical content of the requirements in this PAD, please contact: Airbus Helicopters (Technical Support), E-mail: TechnicalSupport.Helicopters@airbus.com and support.technical-dyncomp.ah@airbus.com; and open a technical Event via Airbus World.

