



# National Transportation Safety Board Aviation Accident Final Report

---

<b>Location:</b>	Merced, California	<b>Accident Number:</b>	WPR22LA140
<b>Date &amp; Time:</b>	April 1, 2022, 12:15 Local	<b>Registration:</b>	N9287U
<b>Aircraft:</b>	Bell OH-58A	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>	Collision with terr/obj (non-CFIT)	<b>Injuries:</b>	1 Minor
<b>Flight Conducted Under:</b>	Part 137: Agricultural		

---

## Analysis

The pilot in the helicopter reported that, he was conducting an agricultural aerial application flight. Before he started the spray operation, he overflew the field to identify obstacles. While approaching the northeast corner of the fields from the south, he overflew one set of wires, “ducked down” into the corner to spray, and pulled up as he approached the edge of the field. As he pulled up, he saw wires he had not seen before and tried to hit them with the wire cutter installed on the helicopter. The helicopter impacted the wires, descended, and impacted the ground. The helicopter sustained substantial damage to the fuselage. The pilot reported that there were no preaccident mechanical failures or malfunctions with the helicopter that would have precluded normal operation.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot’s failure to see and avoid wires while conducting an aerial application flight, which resulted in a wire strike and ground impact.

## Findings

---

Personnel issues	Monitoring environment - Pilot
Environmental issues	Wire - Effect on operation

## Factual Information

### History of Flight

<b>Maneuvering-low-alt flying</b>	Collision with terr/obj (non-CFIT) (Defining event)
-----------------------------------	---

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	62, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Right
<b>Other Aircraft Rating(s):</b>	Helicopter	<b>Restraint Used:</b>	4-point
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	
<b>Medical Certification:</b>	Class 2 With waivers/limitations	<b>Last FAA Medical Exam:</b>	February 15, 2022
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	February 16, 2022
<b>Flight Time:</b>	2336 hours (Total, all aircraft), 647 hours (Total, this make and model), 1970 hours (Pilot In Command, all aircraft), 35 hours (Last 90 days, all aircraft), 35 hours (Last 30 days, all aircraft), 4.2 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Bell	<b>Registration:</b>	N9287U
<b>Model/Series:</b>	OH-58A	<b>Aircraft Category:</b>	Helicopter
<b>Year of Manufacture:</b>	1971	<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	71-20428
<b>Landing Gear Type:</b>	Skid	<b>Seats:</b>	2
<b>Date/Type of Last Inspection:</b>	February 28, 2022 100 hour	<b>Certified Max Gross Wt.:</b>	3200 lbs
<b>Time Since Last Inspection:</b>	178 Hrs	<b>Engines:</b>	1 Turbo shaft
<b>Airframe Total Time:</b>	6369 Hrs at time of accident	<b>Engine Manufacturer:</b>	Rolls Royce
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	250-C2-OC
<b>Registered Owner:</b>		<b>Rated Power:</b>	420 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	Agricultural aircraft (137)

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KMCE, 153 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	12:53 Local	Direction from Accident Site:	55°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	332°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.93 inches Hg	Temperature/Dew Point:	22° C / 3° C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	Unknown

## Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	37.189404, -120.68928

## Administrative Information

Investigator In Charge (IIC):	Baker, Daniel		
Additional Participating Persons:	Jason Alves; FAA-FSDO; Fresno, CA		
Original Publish Date:	July 13, 2022	Investigation Class:	4
Note:	The NTSB did not travel to the scene of this accident.		
Investigation Docket:	<a href="https://data.nts.gov/Docket?ProjectID=104882">https://data.nts.gov/Docket?ProjectID=104882</a>		

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available [here](#).